



Service Bulletin #264

SB-264
(021708)
ECR_8847


Which Design Do You Have?

Ford F-250/F-350/F-450 (Single and Dual Rear Wheel) 57396 and 88396 Four-Wheel-Drive Underbracket Redesign

Background: The lower bracket for this kit was redesigned to reduce complexity and installation time.

First-Gen Design

If the air spring's lower bracket is attached by two bolts holding a retainer plate alongside the vehicle's leaf spring mount, it is the first-generation design.



Part numbers

5" hex bolt: 17184

L bracket: 10886

Retainer plate: 10861

Lower bracket, with welded cup: 03990
(not shown)

Instruction manual links

LoadLifter 5000 Ultimate MN-824

Kit no.: 88396

<https://www.airliftcompany.com/manuals/MN-824.pdf>

LoadLifter 5000 MN-770

Kit no.: 57396

<https://www.airliftcompany.com/manuals/MN-770.pdf>

Second-Gen Design

If the bottom plate is attached by a U-bolt, it is the second-generation design.



Part numbers

U-bolt: 11717

Lower bracket: 03997

Lower bracket cup: 03998

Instruction manual link

LoadLifter 5000 series MN-1042

Kit nos.: 57396, 88396

<https://www.airliftcompany.com/manuals/MN-1042.pdf>

Thank you for purchasing Air Lift Products! For technical support, please call (800) 248-0892
Air Lift Company • P.O. Box 80167, MI 48908-0167 • (517) 322-2144 • Fax: (517) 322-0240 • www.airliftcompany.com